



Details:

Model No.	S-WS8061
Measuring item	Temperature + Humidity
Feature	Comfort Level Indicator
Key operation	[MAX/MIN],[CLEAR]
Key operation(at the back)	[°C/°F]
Temperature range	(-50°C~ 70°C) (-58°F~ 158°F)
Humidity range	10%~99%RH
Temperature resolution	0.1°C
Humidity resolution	1%RH
Temperature accuracy	±1°C(±2°F)
Humidity accuracy	±5%RH
Power supply	1.5VAAA x 2 Battery
LCD size	87x70mm
Unit size	110*100*20mm